

July 12, 2001

**KST UHF operation memorandum for July 9-10 BY S. Nozawa**

Experiment name: SP-NI-TG2 (cp1lt\_tg2\_ni)

Elan files: cp1lt\_tg2\_ni.elan, cp1lk\_tg2\_ni.elan, cp1ls\_tg2\_ni.elan

Directory: /kst/exp/cp1lt\_tg2\_ni (cp1lk\_tg2\_ni , cp1ls\_tg2\_ni )

Pulse scheme: cp1lt

Start time: 10:00 UT on July 9, 2001

End time: 12:15 UT on July 10, 2001

Participants: Satonoti Nozawa, Sawako Maeda (PI), Seiko Imaida  
(ESR operation has been conducted by Yasunobu Ogawa)

Before our experiment: Nothing

We made a test from 7 UT to 9 UT on the same day, and found that  
the receiver (or related materials) were problematic.

After our experiment: Nothing

-----  
**Note: (time in UT)**

**July 9**

**10:00 START without Kiruna: Kiruna has a problem with "polarizer"**

1.2 MW -> 1.6 MW -> 1.2 MW

10:15 Antenna position is wrong: due to EROS bug

(After "stopexp" we need to logout EROS and restart EROS at any sites used.)

10:18 Tromso recovered

10:46 Sodankyla recovered

**\*\*\* Failue due to "high power reflector" occured OFTEN \*\*\***

11:58 Transmitter failure: Kind of "safety lock":it takes 10 minutes to get the transmitter on  
-12:14 1.6 MW

12:30 Tx down (means failue of transmitter occurred:usuall due to high reflected power)

12:43 Tx down

Tx = 1.2 MW

13:16 Tx down

**13:39 Kiruna recovered (some time before)**

14:14, 15:52, 16:04, 16:07, 16:17, 16:27, 16:53 Tx down

16:56 sod setclockdely (but, nothing happened)

17:03, 17:11, 18:22, 18:58, 19:13, 19:33, 19:48, 19:58 Tx down

20:07 Tx down and Power down to 1.1 MW

20:13 System stopped due to high room temperature (in antenna?): it was above 40 deg !

20:25 RECOVERED  
20:57 Tx down  
1.8MW

## July 10

0:07, 00:11-00:13, 00:27-00:30, Tx down  
1.5 MW  
00:42-00:46 Tx down  
00:46 1.3MW

**01:31 sod antenna position was strange: not followed by the command**  
**AZACU 308.02 ELACU 18.01 <--- pointing**  
**AZCOM 341.49 ELCOM 18.02 <--- command**

**This kind of "problem" occurred when tromso pointing north AND south,  
but NOT always.**

01:32- 01:37 Txdown

02:07 Tx down  
02:23- 02:33 Tx down: a electric board was changed ?  
02:45, 02:50, 03:06 Tx down

**03:46 sod Az got strange:**  
**AZACU 308.02 ELACU 48.32 <--- pointing**  
**AZCOM 243.60 ELCOM 35.11 <--- command**

**04:33 sod Az got strange**  
**05:08 sod Az got strange**

05:38, 06:07 Tx down  
06:50 sodankyla Az got strange  
07:06, 07:14, 08:05, 08:09, 08:43, 09:44 Tx down  
1.6 MW ?  
10:09, 10:11, 10:16, 10:22 Tx down

11:04 Connection with Kiruna down (they closed the connection due to thunderstorm ?)  
11:55 I phoned Kiruna and confirmed Kiruna was running  
12:07 Connection with Kiruna recovered

**12:15 Tromso antenna got a problem. Serious!!!!**  
**During movement from FA to North**  
Observation is stopped

**12:30 END**

---

Summary:

Transmitter failure occurred so often. So, we reduced the power and made experiment with 1.2 MW. Very often we got no-spectra view with rtg at remote. I am not sure if this is a problem with data or just display (rtg), but it seems like a problem of "clockdelay" ?

---